

Approved For Release 2000/06/14 : CIA-RDP78-06505A000700060040-0

INDEX: YES NO _____
 CLASSIFY TO FILE NO. _____
 X-REF TO FILE NO. _____
 FILE RID RET. TO BRANCH
 DESTROY SIG. _____
 FROM *Dissem BY 24*

CLASSIFIED MESSAGE

TOTAL COPIES

14

SECRETGROUP I
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

PERSON/UNIT NOTIFIED

REPRODUCTION PROHIBITED

1	<i>RE</i>	5	<i>RE</i>
2		6	<i>PD</i>
3		7	
4		8	

ACTION

Logs-4 RID COPY

ADVANCE COPY

 ISSUED SLOTTED TUBED

UNIT

TIME

BY

INFO

FILE, VR, FE-

25X1A	INFO DIRECTOR	17 JUN 66 IN 39879
-------	---------------	--------------------

SECRET 171611Z CITE LOGISTICS 5780

25X1A

INFO DIRECTOR

REGRET MISUNDERSTANDING. FOLLOWING KEYED TO REF:

PAR 2. POSSIBLE TO REBUILD GENERATOR FOR HIGHER KW.

HOWEVER COST OF UPGRADING ENGINE (WHICH WOULD BE NECESSARY)

IS \$10,600 OR HALF THE PRICE OF NEW 350 KW UNIT. THIS PLUS

COST OF UPGRADING GENERATOR MAKES COST PROHIBITIVE. ASSUME

YOU WILL REPAIR DAMAGED GENERATOR TO ORIGINAL CONDITION.

PAR 3. ON BASIS OF ABOVE PAR, RECOMMEND REBUILD OTHER
GENERATORS TO ORIGINAL CONDITION IF INDICATIONS OF FAILURE
PRESENT.PAR 4. AND PAR 8. ASSUME YOU REQUIRE ONE NEW REGULATOR
COMPLETE AND THE ITEM SPECIFIED PAR 8 IS THE REQUIRED (UPRATED)
CAPACITY AND NOT PRESENT NAMEPLATE CAPACITY.

PAR 7. PROCUREMENT AUTHORITY GRANTED. SUGGEST

25X1A

25X1A REQUISITION FROM

SECRET *Re parts on hand to restore damaged generator*

BT

SECRET

Approved For Release 2000/06/14 : CIA-RDP78-06505A000700060040-0